



IMPORTANT

Land Cruiser 70, 80, 100 Series




Before

A (1:1)



After

B (1:1)



NOTE:

On some year models of Landcruiser the knuckles protrude further and may require slight grinding to clear the bottom of the pads in the Powerbrake caliper. Check carefully if grinding is required on **BOTH** knuckles before tightening the caliper to the bracket.

Only grind what is necessary!

